

SECRET

NO FOREIGN DISSEM

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to N-3819/73  
14 October 1973  
Page 1 of 2

Copy \_\_\_\_\_

REFERENCE TO:

DAMAGED PETROLEUM STORAGE  
PORT SAID, EGYPT

1. SIGNIFICANCE:


BOMB DAMAGE WAS OBSERVED AT THE  
PETROLEUM STORAGE DEPOT IN PORT  
SAID.

2. LOCATION:

THE PORT SAID PETROLEUM STORAGE  
DEPOT  IS AT THE  
SOUTH EDGE OF THE CITY AT 31-14-18N  
032-18-03E.

3. MISSION READOUT:

ONE LARGE FLOATING ROOF TYPE POL  
TANK HAD ROOF AND SIDE DAMAGE. A SMALLER TANK HAD EXTENSIVE  
ROOF AND SIDE DAMAGE WITH SOME PROBABLE POL SPILLAGE AROUND  
THE BASE OF THE TANK AND THE TANK NEXT TO IT. THERE WAS AN  
OIL SLICK EXTENDING INTO THE SUEZ CANAL FROM A PROBABLE



These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

WARNING NOTICE  
Sensitive Intelligence Sources  
and Methods Involved.

SECRET  
NO FOREIGN DISSEM

**SECRET**

NO FOREIGN DISSEM  
(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to N-3819/73  
14 October 1973

Page 2 of 2

RUPTURED PIPELINE AT THE STORAGE DEPOT.

ENLARGEMENT FACTOR: 7X

IEG/SGD/AMEAB

COMMENTS AND QUERIES REGARDING THIS REPORT ARE WELCOMED. THEY  
MAY BE DIRECTED TO [REDACTED] OF AMEAB/SGD/IEG/NPIC, CODE 143,

[REDACTED]

[REDACTED]

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

**SECRET**

NO FOREIGN DISSEM